Title	Fractography of shear failure surface of softwood decayed by brown-rot fungus
Author(s)	Takanashi, Ryuya; Ishihara, Wataru; Sawata, Kei; Sano, Yuzou; Azuma, Tomonori; Mori, Mitsunori; Koizumi, Akio; Sasaki, Yoshihisa; Hirai, Takuro
Citation	Journal of Wood Science, 60(3), 186-193 https://doi.org/10.1007/s10086-014-1393-3
Issue Date	2014-06
Doc URL	http://hdl.handle.net/2115/60045
Type	article (author version)
File Information	Fractography of shear failure surface ofpdf

[Instructions for use](#)

Fractography of shear failure surface of softwood decayed by brown-rot fungus

Type of article: Original Article

Author's name: Ryuya Takanashi, Wataru Ishihara, Kei Sawata, Yuzou Sano, Tomonori Azuma, Mitsunori Mori, Akio Koizumi, Yoshihisa Sasaki, Takuro Hirai

Ryuya Takanashi, Kei Sawata (corresponding author), Yuzou Sano, Akio Koizumi, Yoshihisa Sasaki, Takuro Hirai

Research Faculty of Agriculture, Hokkaido University, N9 W9, Sapporo, 060-8589, Japan

E-mail: ksawata@for.agr.hokudai.ac.jp

TEL: +81 11-706-2528, FAX: +81 11-706-3636

Wataru Ishihara

Research Faculty of Agriculture, Hokkaido University, N9 W9, Sapporo, 060-8589, Japan

Butsurin Corporation, Tokyo 136-8543, Japan

Tomonori Azuma, Mitsunori Mori

Forest Products Research Institute, Hokkaido Research Organization, 1-10 Nishikagura, Asahikawa 071-0198, Japan

Keywords: Scanning electron microscopy, Failure morphology, Average roughness, Shear strength

Footnote: Part of this study was presented at the 42th Annual Meeting of the Hokkaido Branch of the Japan Wood Research Society, November 2010, Sapporo, Japan

Abstract

In order to investigate shear failure surface of decayed wood, wood pieces of *ezomatsu* (*Picea jezoensis*) were exposed to brown-rot fungus (*Fomitopsis palustris*), and standard shear test in radial plane was conducted. The failure surfaces were examined by scanning electron microscopy and surface roughness measurements were also conducted. Transwall failure that the crack elongated parallel to the tracheid axis was observed in the earlywood region through all phases of decay. Intrawall failure principally occurred in the latewood region on the early phase of decay. When decay progressed considerably, transwall failure that the crack elongated perpendicularly to the tracheid axis occurred. And transwall failure was also dominant failure morphology in the latewood region. Fragments of tracheids which were partly peeled out from S₂ layers were observed in some specimens. Size and appearance frequency of fragments of tracheid was smaller and lower when decay progressed. Arithmetic average roughness, which was the index of fragment size and appearance frequency, had positive correlation to shear strength ratio. Especially, line surface roughness of radial direction, which was measured across the radial files of tracheid, had the highest correlation to the shear strength ratio. The surface roughness would be a good indicator to evaluate the decay degree.

Keywords:

Scanning electron microscopy, Failure morphology, Average roughness, Shear strength

Introduction

Mechanical properties of wood materials are degraded by brown-rot fungus. Even if a wood material exposed to brown-rot fungus shows little mass loss and change of surface color, its strength often decreases significantly [1, 2]; therefore, studies of wood degradation process in incipient stages of decay caused by brown-rot fungus is needed to understand mechanism of strength deterioration.

Numerous studies that are based on the biological, biochemical and mechanical viewpoints [3-11] have been performed on the wood deterioration by brown-rot fungus. Especially, because the strength deterioration of decayed wood may largely affect safety of timber structures, estimation of degree of deterioration have been performed on partially decayed wood. Methods applied in such studies to date are the pin-penetration depth [5, 6], acoustic emission [7, 8], infrared spectra [9, 10], X-ray microdensitometry [11]. However, the values obtained by those were influenced by moisture content and distribution of decay. Thus these methods need non-decayed specimens with same condition. In addition, methods of detection of incipient stages of decay are limited. Detection of the decayed part of wood, estimation of decay degree of wood, and evaluation of the residual strength of decayed wood are desired.

Fractography is effective to observe a failure surface and understand failure morphology. For sound wood, Saiki et al. [12] examined tensile failure surfaces. Some studies [13-15] carried out the shear parallel to the grain tests, and stated the differences of failure morphology between the earlywood and latewood regions using scanning electron microscopy (SEM) images. Imamura [7] and Furukawa [16] examined tensile broken surface of deteriorated wood. Some observations of tensile failure surface were reported on wood decayed by brown-rot fungus; however, little

investigation has been performed on the shear failure surface of wood decayed by the brown-rot fungus.

Therefore, we carried out the shear parallel to the grain tests with wood decayed by a brown-rot fungus, and observation of its shear failure surface by SEM. The relations between failure morphology and the extent of decay were also determined using SEM images. Moreover, besides the microscopic observations, three-dimensional shapes of failure surface were quantitatively evaluated using surface roughness. The deterioration of wood exposed to the brown-rot fungus was estimated by comparing the surface roughness and the shear strength.

Materials and Methods

Specimens

The shear parallel to the grain tests were conducted on ezomatsu (*Picea jezoensis*). Eighteen shear specimens [20 (T) × 20 (R) × 30 (L) mm] that had radial shear planes were cut from 4 solid lumbers (A, B, C, and D). The control specimens were also cut from same lumbers. These control specimens were end-matched to each specimen for decay. Table 1 shows the list of specimens.

Decay treatment

To induce decay through a shear plane along grain in the shear specimens, all the surfaces of specimen were coated with epoxy resin first. After epoxy resin hardened, the slit of 1 mm in width and 10 mm in depth was cut in the radial plane (Fig. 1). Then, the specimens were sterilized with ethylene oxide gas and placed in grass bottles containing the brown-rot fungus culture of *Fomitopsis palustris*. Nutrient

solution was pure water including 4% D-glucose, 1.5% malt extract, and 0.3% peptone. The exposed specimens were placed in a room kept at constant temperature (24 °C) for period as shown in Table 1. The sterilizing of specimens and decay treatment were conducted in Forest Products Research Institute, Hokkaido Research Organization, Asahikawa, Japan.

Measurement of shear strength

Shear parallel to the grain tests, block shear tests, according to JISZ2101 [17] were performed on specimens after specimens were conditioned to air-dry humidity control and shaping the notch. The tests were terminated when the specimens were separated into two blocks. Average moisture content of specimens after shear test and the standard deviation of them were 8.6% and 0.74%, respectively.

SEM

Small blocks (L:R:T = 6:6:1~2 mm) including shear failure surface were cut from the specimens. The failure surfaces were visually flat in the loaded ends, but heavily rough in the bottom ends as shown in Fig. 2. This may be caused by the grain and the distributions of stress perpendicular to the grain and shear stress along to shear plane [18]. In this study, the blocks for SEM were cut near the notch as shown in Fig. 3. After dried in a desiccator, the blocks were mounted onto specimen stubs for SEM with an electron conductive paste, and then they were coated with platinum by vacuum evaporation. The instrument used for the SEM was the JSM-6301F (JEOL Ltd.) operated at an accelerating voltage of 2.5 kV.

Surface roughness measurement

After the SEM, the surface roughness of all exposed specimens was measured using laser microscope (VK-9500 KEYENCE Ltd.). The slice samples for the SEM were used in this measurement. This microscope can measure height of a sample surface of 768×1024 pixels. Magnifying power was 10 times and the pitch of measuring surface and height were $1.383 \mu\text{m}$ and $0.5 \mu\text{m}$, respectively. The measuring area was 1.5 mm^2 , and was adjusted to include the earlywood and latewood regions near the edge of notch.

The arithmetic average roughness was adopted as an index of surface roughness in this study. It was calculated by the analysis software (VK-H1A9 KEYENCE Ltd.). The average line surface roughness (R_{aL}) and average plane surface roughness (R_{aA}) were calculated from the variation of height in measuring area as follows:

$$R_{aL} = \frac{1}{l} \int_0^l |f(x)| dx \quad (1)$$

$$R_{aA} = \frac{1}{A} \iint_A |f(x, y)| dx dy \quad (2)$$

where l is measured length, A is measured area, $f(x)$ and $f(x, y)$ are difference between the roughness profile and the average height.

The line surface roughness was defined as the values of the sum of difference between the roughness profile and the average height in the measured range divided by the measured length [19]. Roughness profiles and average line surface roughness of C5 and C3 specimens are shown in Fig. 4 as the example. The high-pass filter that had cutoff value of 0.8 mm was adopted to obtain the roughness profile from the measurement values. The line surface roughness was measured in the longitudinal

direction in the earlywood, longitudinal direction in the latewood, and radial direction. The measured lines of the longitudinal direction in the earlywood and latewood were set parallel to a tracheid in the earlywood and latewood regions, respectively. In the case of the radial direction, the measured lines were set across a radial file of tracheids as not including rays. The line surface roughness had a little difference among some measured lines from preliminary tests. Therefore, those measured lines were manually determined. Pair of line surface roughness was obtained from each direction and its average values were used for roughness index of specimens. The plane surface roughness was expansion of line surface roughness, and was calculated from the whole measured area.

Results and discussion

SEM

After the decay treatment and the shear parallel to the grain tests, discoloration due to wood decay was observed on the slit surface and in narrow regions that extended longitudinally from the edge of the slit in the decayed specimens, but no visible damage was observed on the loading and supporting surfaces of the specimens, and all specimens broke at a corner of the notch. The decay procedure of this study proved to be an effective method to investigate the shear strength of decayed wood.

Failure morphology of tracheids was determined from the image of the magnification of 25 times. This image included a 3.6 mm (L) $\times$ 4.9 mm (R) area of a 6mm $\times$ 6mm specimen block. And then, the representative failure morphology of tracheids was observed in detail by higher magnification images. Some studies [13-15] that conducted on shear parallel to the grain argued difference of failure morphology

between the earlywood and latewood. According to these studies, failure morphology is affected by thickness of the cell wall. In softwood, transwall failure, which is rupture of S_2 secondary cell wall layer resulting in exposure of cell lumina, frequently occurs in earlywood region consisting of thin-walled tracheids. By contrast, intrawall failure predominantly occurs at and around the interface between S_1 and S_2 layers of thick-walled tracheids in latewood region. Because brown-rot fungus decomposes cellulose, and degrades cell walls; failure morphology of heavily-decayed specimens would be different from that of lightly-decayed specimens, and failure morphology of tracheid could be index of decay degree.

Figures 5, 6 and 7 show a sheared plane of D1 specimens that were exposed to decay fungus for 7 days (Table 1). The failure morphology was different between the earlywood and latewood regions. The lumina of tracheids are commonly visible as a result of fragment occurrence of transwall failure that extends along cell axis (Fig. 6). By contrast, lumina of tracheids are invisible in the latewood region (Fig. 7). In this case, ruptured layers of tracheid walls can be determined by the microfibril angle (MFA) [15]. On the failure planes of latewood region, MFA was mostly 20~30 degrees or 70~80 degrees. This indicates that the intrawall failure in latewood tracheids occurred at and around boundaries between S_1 and S_2 . These features in failure morphology found in slightly-decayed woods are similar to failure morphology reported for sound wood [13, 15].

Figure 8 shows a sheared plane of B3 specimen which was exposed to decay fungus for 14 days (Table 1). The failure morphology of B3 specimen resembles that of D1 specimen; however, some tracheids were cut off perpendicularly to the grain in the earlywood region. These failures are also classified into transwall failure; however, the

orientation of failure differs from the case of slightly-decayed specimens. Thus, transwall failure that the crack elongates perpendicularly to the tracheid axis is distinguished from transwall failure that the crack elongates parallel to the tracheid axis. Figure 9 shows sheared planes of C3 specimen which was exposed to decay fungus for 28 days (Table 1). Transwall failure commonly occurred in not only earlywood but also latewood regions. Failure morphology in the latewood region should be changed as cell walls of tracheids become thin. Moreover, many transwall failures perpendicular to the tracheid axis in the earlywood region were present in this failure morphology. The frequency of existence of transwall failure perpendicular to the tracheid axis in the earlywood region and transwall failure in the latewood region would be features of decay degree.

From the results described above, failure morphology was classified into 3 modes (Fig. 10). Mode 1 was transwall and intrawall failures in the earlywood and latewood regions, respectively. Transwall failures parallel to the tracheid axis were dominant in this mode. Mode 2 was also transwall and intrawall failures in the earlywood and latewood regions, respectively. A characteristic of the transwall failures, which is not dominant in mode 1, is that the crack elongated perpendicularly to the tracheid axis. When such failures were observed in the majority of the image of the magnification of 25 times, the failure morphology was decided to mode 2. Mode 3 was transwall failure in both the earlywood and latewood regions. When transwall failures were observed in the majority of latewood region, the failure mode was decided to mode 3. The characteristics of mode 3 was that the tracheid in the latewood region was cut both parallel and perpendicularly to the tracheid axis and the transwall failures perpendicular to the tracheid axis were also dominant in the earlywood region. The

transition of failure morphology proceeded continuously with an extent of decay.

The shear strength and the failure modes of all specimens are shown in Table 1. Figure 11 shows the relations between the ratio of shear strength of decayed specimen to that of control specimen and failure modes. Because wood strength has variation, shear strength of specimen with little or a little degradation may be larger than that of end-matched control specimen. Four specimens with failure mode 1 and one specimen with failure mode 3 had the shear strength ratio of 1.0 or more. The former would be little degraded by decay. Although the latter was observed the transwall failures in the latewood region, the partial degradation would little cause the shear strength loss. Some of specimens that had failure modes 2 and 3 showed small shear strength ratio and significant strength loss was observed in a specimen with failure mode 3. Specimens with large strength loss were exhibited different failure morphology in comparison to the others.

On sheared plane of sound wood, peeling out of secondary wall of tracheid have been observed, called “flags” by Côté and Hanna [13]. The peeling out of tracheid is usually observed in the earlywood region. The peeling out of tracheid was observed in the specimen with high shear strength in this study (Fig. 5). As shear strength was decreased, size of fragment of tracheid seemed to be smaller and its appearance frequency of fragment seemed to be lower. In addition, specimens with considerable small shear strength showed no fragment of tracheid caused by peeling out (Fig. 9). The size and appearance frequency of fragment of tracheid may depend on the extent of decay. The extent of decay, which includes incipient decay to significant decay, could be evaluated by investigation of fragment of tracheid. Therefore, the shape of failure surface was quantitatively evaluated by the surface roughness.

Surface roughness measurements

The size and appearance frequency of fragment of tracheid affected the roughness profile of failure surface. As shown in Fig. 4, the C3 specimen which had little strength loss showed significantly ragged surface while the roughness profile of the C5 specimen which showed large strength loss exhibited small variation. This study conducted the calculation of 4 kinds of the arithmetic average roughness, which were the line surface roughness in the longitudinal direction in the earlywood, longitudinal direction in the latewood and radial direction, and the plane surface roughness. Figure 12 shows the relations between the ratio of shear strength of decayed specimen to that of control specimens and average roughness, including regression formulas of the logarithm. Regardless of kind of average roughness, the shear strength tended to decrease with decreasing the average roughness. The relations between the strength ratio and the line surface roughness in the radial direction showed the highest correlation of the 4 kind of surface roughness.

From the results described above, the fragments of tracheid caused by peeling out might be reliable index to evaluate strength loss. The line surface roughness in the radial direction was better appropriate index to estimate the degree of decay. In addition, measured lines were designed manually in this study, thus, the relative simple measurement method, for example only one line measuring, can be effective to detect degree of decay.

The results of observation by SEM and measurement of surface roughness showed that size of fragment of tracheid was smaller and its appearance frequency of fragment was lower as decay progressed. It is known that brown-rot fungus

decomposes cellulose chain [3]. Change of surface roughness of the failure plane might show qualitative change of cell wall by decay. Reduction in size and appearance frequency of fragment of tracheid might be evidence of decomposition of cellulose chain of cell wall by decay.

Conclusions

Tests of shear parallel to the grain in radial plane and fractography of the shear failure surface were conducted for *ezomatsu* exposed to the brown-rot fungus *Fomitopsis palustris*. The results obtained can be summarized as follows:

1. Transwall failure that the crack elongated parallel to the tracheid axis occurred in the earlywood region irrespective of degree of decay.
2. Transwall failure that the crack elongated perpendicularly to the tracheid axis occurred when wood was decayed significantly.
3. Intrawall failure was dominant failure morphology in the latewood region in incipient stages of decay. When decay progressed considerably, the failure morphology in the latewood region changed from intrawall failure to transwall failure.
4. Size and appearance frequency of fragment of tracheid caused by peeling out was dependent on degree of decay. As decay progressed, size of fragment of tracheid was smaller and appearance frequency of fragment of tracheid was lower.
5. There was positive correlation between shear strength ratio and average roughness of shear failure surface. Line surface roughness in the radial direction could be reliable indicator to estimate strength loss.

Acknowledgement

The authors gratefully acknowledge support in the laser microscopic measurement by Prof. Yasumitsu Uraki and Ms. Yuka Tasaki, and SEM photographing by Dr. Masanori Yasui.

Reference

- [1] Richards DB (1954) Physical changes in decaying wood. J Forest 52:260-265
- [2] Takahashi M, Nishimoto K (1967) Studies on the mechanism of wood decay (I). : Changes in strengths of BUNA and SUGI wood as decay proceeds (in Japanese). Wood Research 41:75-89
- [3] Kleman-Leyer K, Agosin E, Conner AH, Kirk TK (1992) Changes in molecular size distribution of cellulose during attack by white rot and brown rot fungi. Appl Environ Microbiol 58:1266-1270
- [4] Munir E, Yoon JJ, Tokimatsu T, Hattori T, Shimada M (2001) A physiological role for oxalic acid biosynthesis in the wood-rotting basidiomycete *Fomitopsis palustris*. Proc Natl Acad Sci USA 98:11126-11130
- [5] Thaler N, Lesar B, Humar M (2012) Correlation between brown rot decay and Pilodyn measurements. Eur J Wood Prod 70:893-895
- [6] Toda M, Mori M, Ohashi Y, Hirai T (2010) Effect of wood decay on the shear performance of nailed timber joint (in Japanese). Mokuzaigakkaishi 56:41-47
- [7] Imamura Y (1990) Detection of decay and termite attack in wood using AE monitoring (in Japanese). Wood Research and Technical Notes 26:38-60
- [8] Raczkowski J, Lutomski K, Moliński W, Woś R (1999) Detection of early stages of wood decay by acoustic emission technique. Wood Sci Technol 33:353-358
- [9] Green B, Jones PD, Nicholas DD, Schimleck LR, Shumulsky R (2011) Non-destructive assessment of *Pinus* spp. wafers subjected to *Gloeophyllum trabeum* in soil block decay tests by diffuse reflectance near infrared spectroscopy. Wood Sci Technol 45:583-595
- [10] Takahashi M, Nishimoto K (1967) Studies on the mechanism of wood decay (2) :

Changes in infrared spectra of BUNA and SUGI wood as decay proceeds. Wood Research 42:1-12

- [11] Macchioni N, Palanti S, Rozenberg P (2007) Measurements of fungal wood decay on Scots pine and beech by means of X-ray microdensitometry. Wood Sci Technol 41:417-426
- [12] Saiki H, Furukawa I, Harada H (1972) An observation on tensile fracture of wood by scanning electron microscope (in Japanese). Bulletin of the Kyoto University Forests 43:309-319
- [13] Côté WA, Hanna RB (1983) Ultrastructural characteristics of wood fracture surfaces. Wood Fiber Sci 15:135-163
- [14] Müller U, Sretenovic A, Gindl W, Grabner M, Wimmer R, Teischinger A (2004) Effects of macro- and micro-structural variability on the shear behavior of softwood. IAWA Journal 25:231-243
- [15] Gindl W, Teischinger A (2003) Comparison of the TL-shear strength of normal and compression wood of European larch. Holzforschung 57:421-426
- [16] Furukawa I (1988) Studies on safety in timbers and woody materials (I) : Fractographic approach to evaluating the brashness of wood (in Japanese). Research bulletin of the Tottori University Forests 17:151-169
- [17] JIS Z 2101 (2009) Methods of test for wood (in Japanese). Japanese Industrial Standard Association, Tokyo
- [18] Okusa K (1980) Studies on the shearing of wood: Especially on the elastic-plastic theory and fracture mechanics: III. On the stress singularity and the energy release rate in the chair-type (JIS) shearing specimen (in Japanese). Bulletin of the Faculty of Agriculture, Kagoshima University 30:201-215

[19] JIS B 0601 (1994) Surface roughness - Definitions and designation (in Japanese).

Japanese Industrial Standard Association, Tokyo

Figures legends

Fig. 1 Dimensions and making procedure of the shear parallel to the grain tests specimen

Fig. 2 Shapes of cracking at the loaded side and bottom side of the specimen

Fig. 3 Sample collection from shear specimen for SEM

Fig. 4 Roughness profiles and average line surface roughness of C5 and C3 specimens.

Note: R_{aL} : Average line surface roughness

Fig. 5 Shear failure surface of lightly-decayed specimen (D1)

Fig. 6 Enlargement of the earlywood region of D1 specimen showing transwall failure.

Fig. 7 Enlargement of the latewood region of D1 specimen showing intrawall failure.

Fig. 8 Shear failure surface of B3 specimen. *Arrow* indicates transwall failure that the crack elongated perpendicularly to the tracheid axis.

Fig. 9 Shear failure surface of considerable decayed specimen (C3)

Fig. 10 Failure modes

Fig. 11 Relations between the ratio of shear strength of decayed specimen to that of control specimen and failure modes.

Note: Failure modes 1 to 3: see Table 1 and Fig. 10.

$F_{s,c}$: shear strength of the control specimen

$F_{s,d}$: shear strength of the decayed specimen

Fig. 12 Relations between the ratio of shear strength of decayed specimen to that of control specimen and arithmetic average roughness

Note: $F_{s,c}$: shear strength of the control specimen

$F_{s,d}$: shear strength of the decayed specimen

Fig. 1

Fig. 2

Fig. 3

Fig. 4

Fig. 5

Fig. 6

Fig. 7

Fig. 8

Fig. 9

Fig. 10

Fig. 11

Fig. 12

Table 1 Outline of shear specimens and results of shear tests.

Specimen No.	Density [kg/m ³]	$F_{s,c}$ [MPa]	Period of decay [days]	$F_{s,d}$ [MPa]	Failure mode
A1	393	6.45	14	6.47	1
A2	401	7.08	21	5.78	1
A3	458	7.61	21	6.11	1
A4	406	6.11	35	5.45	2
B1	433	8.49	7	7.38	1
B2	456	5.70	7	6.71	1
B3	441	6.22	14	3.79	2
B4	431	7.37	14	5.19	1
B5	438	6.92	21	5.60	1
B6	460	8.47	35	8.84	1
B7	437	5.89	35	5.40	3
C1	383	5.11	7	4.84	2
C2	345	4.27	28	4.35	3
C3	387	4.83	28	4.32	3
C4	333	6.17	56	5.45	3
C5	364	5.26	56	1.28	3
D1	525	7.37	7	7.97	1
D2	522	10.23	14	5.97	3

$F_{s,c}$ Shear strength of the control specimen; $F_{s,d}$ Shear strength of the decayed specimen; **Failure mode 1** Transwall failure in the earlywood region and intrawall failure in the latewood region. Cracks of the transwall failure in the earlywood region are almost elongated parallel to the tracheid axis; **Failure mode 2** Transwall failure in the earlywood region and intrawall failure in the latewood region. Cracks of the transwall failure in the earlywood region are frequently elongated perpendicularly to the tracheid axis; **Failure mode 3** Transwall failures in both the earlywood and latewood regions. Cracks of the transwall failure in the earlywood region are frequently elongated perpendicularly to the tracheid axis, and those of the latewood region are elongated both parallel and perpendicularly to the tracheid axis.